

## DP-1 Firmware update

Ver:0E

Svn:2643

Date:2017.09.29

### Firmware update features and changes:

1,The firmware updates solves the problem that all optical input source's frequency will maybe recognize as 88.2KHZ automatically which will cause abnormal sound.

2,Performance updates Improve the system stability.

3,This firmware update contains Ver:EC version update changes:

- 1.Long-pressing function for EQ,MUTE,Source Key invalid.
- 2,It can access to music files from formative NTFS U-Disk in WIN10 and WIN8.
- 3,Support all music file playback under NTFS file.
- 4,Solving the problem of Instantaneous absence of sound for parts of a second when audio source switching.
- 5,Remote control operation will no made the set crash when power on and S.M.S.L logo shows.
- 6,It solves the problem of sampling rate changes frequently.and no happening again for no sound output.
- 7,Solving memory leak of Demuxer MAP3,ALAC issue.
- 8,No noise now if playback APE music file from NTFS U-disk.

4,This firmware update contains Ver:A version update changes:

- 1. Fix bug To fix some FAT32 U-disk or SD Card , when playing CUE FLAC files,switching songsvery slow or no responds.
- 2. Performance updates Improve the system stability.
- 3. Menu updates Add the software version shown in the menu.

---

Firmware update by U-Disk : Save rom.upd file of player firmware into U-Disk root directory.Powering on player.When DP-1 shows SMSL logo,please press left and right button at same time until screen shows”

NO-USB”.Then plug U-Disk into DP-1 to automatically update.When screen appear 100%,update finish.

Warning: When starting the firmware upgrade ,please do not power off or any operation to the player until the upgrade is complete.